Non-Sterile Cleanroom Gowning Procedure

STEP 1: PRE-ENTRY




Bouffant/Hair Net Be sure to contain all hair.



Shoe Covers Contain all laces and tassels.

В



STEP 2: GOWNING



Gowning Gloves Recommended for Class 100 and better.






В

Mask Worn over or under hood. Bend nosepiece first for a snug facial fit.





Hood Ensure snug fit and proper face/neck seal.



Step 6

Coverall

STEP 3

Step into the coverall.

Be sure sleeves and upper garment do not touch bench or floor.

Tuck shoulder panels from hood inside coverall before zipping up.



Boot Covers

STEP 4


Put on boots and pull boots (high-top shoe covers) over legs of coverall.

If cross-over bench is used, transfer each foot to cleaner side of bench as boot is donned.

Goggles Wear goggles/safety glasses when eye protection or additional particulate control

STEP 5

is desired.



Cleanroom Gloves (optional) Place hem of glove over cuff of sleeve. Put on over gowning gloves or remove gowning

gloves or remove gowning gloves and then put on cleanroom gloves.



Non-Sterile Cleanroom Gowning Removal Procedure

STEP 1: IN ORDER



Gloves If two pairs of gloves are worn, remove top pair of gloves, then discard.





Goggles/Safety Glasses Remove and properly contain.




С

M



STEP 2



If coverall is to be used again, either hang it in a controlled environment or prepare for storage.



В

Hood Hang in controlled environment.





Mask Remove and usually discard.




كاك






Step 3




Gloves

It is recommended that gloves be discarded after each change.



Bouffant/Hair Net Usually discard after each change.



Shoe Covers Usually discard after each change.

Customer Service: 1.800.931.3456 www.controlledenvironments.dupont.com

These are recommendations only. Gowning procedures may vary by protocol or company procedures.

Copyright @ 2010 DuPont. The DuPont Oval Logo and The miracles of science" are trademarks or registered trademarks of E.I. du Pont de Nemours and Company or its affiliates. All rights reserved. H-93118-1 2/10

DuPont Controlled Environments



Sterile Cleanroom Gowning Procedure

STEP 1: PRE-ENTRY



Α

Bouffant/Hair Net Be sure to contain all hair.



STEP 3



В

В

Shoe Covers

and tassels.


Contain all laces

Mask Adjust for a snug facial fit. May be worn over or under proper neck seal. hood.


Hood Ensure snug fit and



STEP 2: GOWNING



Wash hands using bactericidal soap and dry thoroughly.



STEP 4

Α

Coverall

Carefully remove coverall from package by holding the inside neck area.

Unfold garment while preventing it from touching the floor, your clothes or bench.

Please exercise care when inserting leg to ensure donning snaps (if used) release and foot clears elastic ankle prior to transferring weight.



First Sterile Gloves Follow aseptic technique by touching only the inside of gloves. Sanitize.



В

Don using aseptic

technique.



Sanitize gloves after donning each article, if required.







STEP 5

Α

Boot Covers Put boots (high-top shoe covers) on using aseptic technique. Tuck coverall legs into boots.

The first boot donned can now be placed in the "clean" side of gowning area.





Α Goggles Adjust for a snug

facial fit.

STEP 6

В

Second Sterile Gloves Complete gowning steps by aseptically donning second pair of sterile gloves over the first pair, making sure the cuffs are securely over the sleeves.





С

inspection in gowning room mirror prior to entry into the sterile cleanroom.



REMOVAL OF STERILE GARMENTS


Enter gowning area from cleanroom and head directly to the "exit gown room" (preferred method).

If no "exit gown room" is available, go directly to the "non-clean" side. usually divided by a bench and/or line.


Remove items in reverse order of gowning procedure and discard.









Goggles





Hood





Outer Gloves

Boot Covers

Coveralls

Mask

F

Inner Gloves Bouffant/Hair Net Shoe Covers

Customer Service: 1.800.931.3456 www.controlledenvironments.dupont.com

These are recommendations only. Gowning procedures may vary by protocol or company procedures.

Copyright @ 2010 DuPont. The DuPont Oval Logo and The miracles of science" are trademarks or registered trademarks of E.I. du Pont de Nemours and Company or its affiliates. All rights reserved. H-93118-1 2/10

DuPont Controlled Environments

н

